

# Senate Bill 680

Sponsored by Senator ATKINSON; Senator BEYER

## SUMMARY

The following summary is not prepared by the sponsors of the measure and is not a part of the body thereof subject to consideration by the Legislative Assembly. It is an editor's brief statement of the essential features of the measure **as introduced**.

Directs Legislative Administration Committee to repair and restore stairwells on either side of rotunda of State Capitol and equip stairwells with modern glass skylights over stairs.

Appropriates moneys from General Fund to Legislative Administration Committee for projects.

Declares emergency, effective on passage.

## A BILL FOR AN ACT

1 Relating to improvements to the State Capitol; appropriating money; and declaring an emergency.

2 **Be It Enacted by the People of the State of Oregon:**

3 **SECTION 1. The Legislative Administration Committee shall repair and restore the**  
4 **stairwells on either side of the rotunda of the State Capitol and equip the stairwells with**  
5 **modern glass skylights over the stairs.**

6 **SECTION 2. There is appropriated to the Legislative Administration Committee, for the**  
7 **biennium beginning July 1, 2011, out of the General Fund, the amount of \$200,000 for the**  
8 **purpose of repairing and restoring the stairwells on either side of the rotunda of the State**  
9 **Capitol and equipping the stairwells with modern glass skylights over the stairs pursuant to**  
10 **section 1 of this 2011 Act.**

11 **SECTION 3. This 2011 Act being necessary for the immediate preservation of the public**  
12 **peace, health and safety, an emergency is declared to exist, and this 2011 Act takes effect**  
13 **on its passage.**

14  
15  

---

  
**NOTE:** Matter in **boldfaced** type in an amended section is new; matter [*italic and bracketed*] is existing law to be omitted. New sections are in **boldfaced** type.