

Figure 1: Example of historical channel features visible in lidar imagery. Full image (left) and enlarged excerpt (right) from DOGAMI Open-File Report O-11-14, Stream channels of the Central Willamette Valley, Benton, Linn, Marion, and Polk Counties, Oregon (<https://www.oregongeology.org/pubs/ofr/O-11-14.pdf>)






Figure 2: Damage to the Port of Tillamook Bay railroad from channel migration of the Salmonberry River
(Courtesy Chris Updegrave, 2/9/2008, <https://www.flickr.com/photos/cupdegrave/2253462031/in/photostream/>)

