




James Fraser
Oregon Policy Advisor
Re: HB 2929-2 (2023)



Juvenile steelhead / *Oncorhynchus mykiss*
Image source: John McMillan / Trout Unlimited

Illegal water storage (OWRD photos).



Source: ODFW / OWRD. Portion of slide deck included in Attachment 2 of TU's written testimony on HB 2929-2.

Large dam on small stream.

Summer 2019

- Coho likely stranded in ditch.
- Only second time BLM biologist has seen creek dry.
- Dry year but not declared drought.

Winter 2022

- Push up dam, diversion remains in place.
- Overtopping fish screen.



Source: ODFW / OWRD. Portion of slide deck included in Attachment 2 of TU's written testimony on HB 2929-2.

Resumption of abandoned diversion dam.

- May 2019.
- Dam rebuilt at old diversion site.
- ODFW records indicate the screen was marked “turned out” since 2011, basically means not taking water.



Source: ODFW / OWRD. Portion of slide deck included in Attachment 2 of TU's written testimony on HB 2929-2.

Unpermitted pumping from streams.



Source: ODFW / OWRD. Portion of slide deck included in Attachment 2 of TU's written testimony on HB 2929-2.

Wetland damaged for grow site.

Before:



Image © 2021 Josephine County GIS

After: grow site terraced into hillside with no erosion control, no water rights.



Source: ODFW / OWRD. Portion of slide deck included in Attachment 2 of TU's written testimony on HB 2929-2.